White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-182307
Estimate date:	December 31, 2024
Customer:	Keith Mcmahon
Phone:	346-555-7326
Insurance claim:	C-1043
Vehicle:	2022 Kia Sorento
VIN:	
License plate:	70B N15

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,759.24
Front bumper cover	1	$1,524.76
Left quarter panel	1	$901.37
Body labor	37.9 hrs	$2,575.32
Paint and materials		$1,622.41
TOTAL		$8,383.10

Appraiser remarks

The vehicle shows front-quarter damage on the driver side, including a cracked bumper cover, a bent front fender support, and a broken headlamp assembly, with scraping that runs toward the wheel well. The pattern lines up with the impact described for a left turn into oncoming traffic. Repair will involve replacing the bumper cover and headlamp, straightening the fenedr support, and refinishing the affected panels. The labor hours requested fit the extent of the damage, and no earlier damage to this vehicle is known from our records. The invoices submitted contain no repeated charges, and the parts list matches the work described.