Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-871988
Estimate date:	February 26, 2024
Customer:	Phillip Marshall
Phone:	713-555-2054
Insurance claim:	C-1044
Vehicle:	2012 Jeep Cherokee
VIN:	HBW4LJLY004SC8872
License plate:	HWV 801

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$546.34
Left quarter panel	1	$663.94
Right front door shell	1	$584.32
Body labor	28.6 hrs	$1,373.92
Paint and materials		$550.50
TOTAL		$3,719.02

Appraiser remarks

The vehicle arrived with damage concentrated on the front driver-side corner, consistent with the left-turn collision as described. The bumper cover, headlamp assembly, fender and hood edge show fresh breaks and scuffing, and the radiator support was checked for misalignment. The repair plan calls for replacing the bumper cover and headlamp, straightening the fender, and refinishing the affected panels. Labor hours appear slightly high for this scope and should be reviewed against standard time. No prior damage to the vehicle is known, and the parts and charges on the file show no repeated billing.