Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-841414
Estimate date:	September 25, 2024
Customer:	Ashley Smith
Phone:	281-555-0586
Insurance claim:	C-1049
Vehicle:	2015 Nissan Altima
VIN:	NPXFMUBC84GMD2770
License plate:	LWS 7302

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,279.57
Hood panel	1	$1,307.78
Right front door shell	1	$915.62
Body labor	37.5 hrs	$2,552.98
Paint and materials		$1,224.79
TOTAL		$7,280.74

Appraiser remarks

Appraiser's remarks: The vehicle shows impact damage to the front left quarter, including a cracked headlamp assembly, a deformed fender, and a bent wheel support on that side. Some of the lower bumper scuffing may be older or from a separate contact, so it is not clear whether evrey mark came from this impact. The repair plan calls for replacing the headlamp and fender, straightening the support, and refinishing the panels. The labor hours requested match the damage described. The invoices show no repeated charges. No earlier damage to the vehicle is known to this office.