Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-646512
Estimate date:	December 5, 2024
Customer:	Deborah Lynch
Phone:	713-555-0858
Insurance claim:	C-1052
Vehicle:	2014 Honda Civic
VIN:	DZ6E36JK045RT8029
License plate:	19F G19

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,097.98
Left quarter panel	1	$918.25
Hood panel	1	$613.05
Body labor	25.1 hrs	$1,706.13
Paint and materials		$863.02
TOTAL		$5,198.43

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with scuffing consistent with a low-speed contact on the driver's side rear quarter panel. The damage pattern lines up with the impact described by the insured. Repair labor hours are in line with the scope of the listed parts, and the parts and paint charges show no repeated entries. However, prior repair records on file show major rear-end damage to this same area from an earlier accident that was never reported to us and is now presented as new. Before approving any payment, the file needs a review of that prior history and of which damage existed before the current incident.