Hall Auto Repair

1823 Joanna Harbor
Katy, TX
Phone 713-555-3435

Repair Estimate

Estimate number:	EST-377217
Estimate date:	2024-06-13
Customer:	Shannon Lewis
Phone:	346-555-5396
Insurance claim:	C-1054
Vehicle:	2013 Chevrolet Malibu
VIN:	R56AS2MM8GBSZ5465
License plate:	3QY I77

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$806.01
Right front door shell	1	$951.05
Left front fender	1	$630.91
Body labor	24.2 hrs	$1,645.43
Paint and materials		$817.46
TOTAL		$4,850.86

Appraiser remarks

The rear quarter panel and bmuper cover show damage that generally matches the impact described for a vehicle turning left into the path of another car. The pattern of crushing and scuffing is consistent across these areas, and no older damage was noted during the inspection or in the records we have. The labor horus listed on the estimate are reasonable for the scope of this repair. Two similar charges appearing on the same day are under review with the shop before the estimate is finalized. Once that check is complete, the plan is to replace the bumper cover, straighten the quarter panel, and refinish the affected sections.