Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-456255
Estimate date:	2024-02-18
Customer:	John Willis
Phone:	832-555-3800
Insurance claim:	C-1064
Vehicle:	2016 Nissan Altima
VIN:	34DX5XYP30VG18856
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,205.47
Front bumper cover	1	$1,161.38
Left front fender	1	$914.31
Body labor	50.2 hrs	$2,411.25
Paint and materials		$1,096.38
TOTAL		$6,788.79

Appraiser remarks

The vehicle presents with damage concnetrated on the rear quarter panel and bumper cover, with the impact area consistent with the reported parking lot collision. The paint transfer and crush depth match the account given. Parts and labor are itemized on the attached estimate, and the labor hours for the planned repair run slightly above what I would expect for this scope, so I have flagged that line for review. Our records show no prior damage to this vehicle. The repair plan calls for replacing the bumper cover, refinishing the quarter panel, and recalibrating the rear sensors before release.