Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-598841
Estimate date:	02/18/2023
Customer:	Justin Mitchell
Phone:	281-555-6821
Insurance claim:	C-1067
Vehicle:	2014 Jeep Cherokee
VIN:	B2M3FGMPXZXA13882
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$773.30
Headlamp assembly	1	$816.06
Left quarter panel	1	$715.04
Body labor	21.2 hrs	$1,444.27
Paint and materials		$630.79
TOTAL		$4,379.46

Appraiser remarks

Vehicle inspected at the body shop following a sideswipe that occurred during a lane change. The damage to the right rear quarter panel, rear door, and adjacent trim is consistent with the reported impact, and the pattern of scraping and crushing lines up with a side-to-side contact. Repair plan calls for replacing the rear door skin, refinishing the quarter panel, and replacing the damaged trim clips. The labor hours submitted fit the extent of the work described. Shop invoices show no repeated charges for the same operations. No prior damage to this vehicle is known from our records or the owner's account.