Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-412512
Estimate date:	2024-01-14
Customer:	Eric Solis
Phone:	281-555-1251
Insurance claim:	C-1068
Vehicle:	2017 Jeep Cherokee
VIN:	
License plate:	312SBG

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$211.93
Hood panel	1	$152.26
Front bumper cover	1	$208.87
Body labor	7.1 hrs	$485.76
Paint and materials		$221.24
TOTAL		$1,280.06

Appraiser remarks

Appraiser's remarks: The left rear quarter panel and rear door show crushed metal and a sprung intrusion beam consistent with a side impact at an intersection, and the pattern of contact matches the account provided. No earlier damage to this vehicle is known from the records reviewed. The repair plan calls for panel replacement, door realignment, and refinishing, and the labor hours listed fit the extent of the damage. Two similar charges submitted on the same day are currently unedr review and have not been approved. Final authorization will follow once that review is complete.