# Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-908281 |
| **Estimate date:** | 2025-05-19 |
| **Customer:** | Wayne Parrish |
| **Phone:** | 832-555-5044 |
| **Insurance claim:** | C-1074 |
| **Vehicle:** | 2018 Toyota Camry |
| **VIN:** | MZ1Y53SP53Y3W1064 |
| **License plate:** | 8Y 47848 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left front fender | 1 | $919.95 |
| Headlamp assembly | 1 | $902.60 |
| Left quarter panel | 1 | $488.42 |
| Body labor | 22.4 hrs | $1,526.20 |
| Paint and materials | | $799.48 |
| TOTAL | | $4,636.65 |

### Appraiser remarks

The vehicle shows damage to the front left corner, including a cracked headlamp assembly, a bent wheel and a torn fender that matches the impact described for a collision during a left turn. Some of the scuffing along the lower bmuper sits a little higher than expected, but the overall pattern agrees with the account. The proposed repair plan covers replacing the lamp, straightening and refinishing the fender, and replacing the wheel, with labor hours that fit the work involved. The billing lines show no repeated charges. Nothing in the file points to earlier damage on this vehicle, so the repair scope can be approved as submitted.