Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-925159
Estimate date:	6-14-23
Customer:	April Simpson
Phone:	713-555-5171
Insurance claim:	C-1079
Vehicle:	2013 Jeep Cherokee
VIN:	
License plate:	ZI 20042

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,180.15
Left quarter panel	1	$946.47
Right front door shell	1	$750.81
Body labor	30.7 hrs	$2,086.65
Paint and materials		$860.12
TOTAL		$5,824.20

Appraiser remarks

Rear quarter paenl and bumper cover show crushed plastic and a creased fender consistent with the reported collision during a left turn. Damage pattern lines up with the impact described by the insured, and no older prior damage has been found on the vehicle. Repair plan calls for replacing the bumper cover, refinishing the quarter panel, and aligning the rear sensor bracket. Labor hours submitted fit the extent of the damage, and the parts and billing records show no duplicated or repeated charges.