Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-999649
Estimate date:	1-29-25
Customer:	Laura Hansen
Phone:	281-555-2833
Insurance claim:	C-1080
Vehicle:	2010 Honda Civic
VIN:	JDLZC3K10E3U57751
License plate:	22Y 168

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,583.12
Left front fender	1	$1,352.20
Headlamp assembly	1	$1,044.12
Body labor	43.8 hrs	$2,980.02
Paint and materials		$1,262.92
TOTAL		$8,222.38

Appraiser remarks

The vehicle shows scraping and a dented rear quarter panel on the passenger side, with paint transfer and a cracked side mirror housing. The pattern of contact is consistent with a sideswipe during a lane change, and the damage lines up with the impact as described. The repair plan calls for panel replacement, refinishing, and mirror assembly, and the labor hours submitted fit the work required. No prior damage to this vehicle is on record. Two similar charges posted on the same day are currently being verified with the shop before the estimate is finalized.