# Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-455493 |
| **Estimate date:** | 17 Apr 2023 |
| **Customer:** | Lindsey Smith |
| **Phone:** | 713-555-1487 |
| **Insurance claim:** | C-1083 |
| **Vehicle:** | 2018 Jeep Cherokee |
| **VIN:** | JBN34YN71TXCP6748 |
| **License plate:** | R17 7EX |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Front bumper cover | 1 | $1,769.25 |
| Right front door shell | 1 | $1,039.63 |
| Left front fender | 1 | $872.73 |
| Body labor | 47.5 hrs | $3,233.07 |
| Paint and materials | | $2,024.58 |
| TOTAL | | $8,939.26 |

### Appraiser remarks

The rear bumper cover is cracked and the left taillight assembly is broken, and the damage across the rear quarter panel lines up well with the impact described in the report. A few older scratches sit along the lower door edge and may predate this loss, so they should be separated out during the write-up. The repair plan calls for replacing the bumper cover and taillight, refinishing the quarter panel, and a standard pre-paint inspection. The labor hours requested fit the scope of this damage, and the parts and charges listed show no repeated entries.