Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-308651
Estimate date:	2024-10-05
Customer:	Amanda Calderon
Phone:	832-555-1751
Insurance claim:	C-1085
Vehicle:	2015 Honda Civic
VIN:	
License plate:	475-PBG

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,394.35
Left quarter panel	1	$970.93
Left front fender	1	$996.65
Body labor	40.8 hrs	$1,958.34
Paint and materials		$1,471.21
TOTAL		$6,791.48

Appraiser remarks

Appraiser remarks: The left rear quarter panel and rear door show crushed metal and a cracked taillight housing, which fits the side impact at the intersection as described. Structural measurements are within tolerance, and no prior damage to this vehicle is known from the file. The repair plan calls for panel replacement, refinishing, and a light-duty frame check. Labor hours run slightly high for this level of damage, so I have asked the shop to justify several operations. The billing records show no repeated charges.