# Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-690988 |
| **Estimate date:** | 4-6-24 |
| **Customer:** | Sean Torres |
| **Phone:** | 832-555-7988 |
| **Insurance claim:** | C-1087 |
| **Vehicle:** | 2015 Chevrolet Malibu |
| **VIN:** | JBG190GS0FA192671 |
| **License plate:** | 42Y 3867 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left front fender | 1 | $429.74 |
| Front bumper cover | 1 | $333.75 |
| Hood panel | 1 | $355.54 |
| Body labor | 15.0 hrs | $1,019.18 |
| Paint and materials | | $487.21 |
| TOTAL | | $2,625.42 |

### Appraiser remarks

Inspection of the front end shows a cracked bumper cover, a bent upper radiator support, and a damaegd hood leading edge, all consistent with a frontal impact at low speed. The pattern of crush and scuffing lines up with the reported collision, and nothing points to older damage on this vehicle. The proposed plan replaces the bumper cover, straightens the support, and refinishes the hood, and the labor hours requested are in line with the repair work described. The repair invoices reviewed show each operation billed once, with no repeated charges.