Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-404900
Estimate date:	1-28-25
Customer:	Anthony Vega
Phone:	281-555-9667
Insurance claim:	C-1095
Vehicle:	2019 Kia Sorento
VIN:	214X0B2X4HNBF1218
License plate:	W60 2KS

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,819.97
Hood panel	1	$1,645.08
Front bumper cover	1	$998.82
Body labor	42.8 hrs	$2,910.28
Paint and materials		$1,364.77
TOTAL		$8,738.92

Appraiser remarks

The left rear quarter panel and rear door show crushed metal and a split seam, with the damage running in line with the side impact described at the intersection. Repair steps are a panel replacement, a door realignment, and refinishing of the affected area. The labor hours recorded fit the damage found. No proir damage to the vehicle is known from the records reviewed. Two similar charges posted on the same day are currently being checked against the repair order before payment is released.