Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-857628
Estimate date:	06/22/2025
Customer:	Jasmin Kelly
Phone:	281-555-8666
Insurance claim:	C-1098
Vehicle:	2010 Nissan Altima
VIN:	0A1U5P3T2WEUH9298
License plate:	2MZP466

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,220.83
Right front door shell	1	$662.73
Front bumper cover	1	$669.55
Body labor	30.2 hrs	$2,053.90
Paint and materials		$997.68
TOTAL		$5,604.69

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including a cracked bumper cover, a bent upper radiator support, and a displaced hood latch. The planned repair is to replace the bumper cover and hood latch, straighten the radiator support, and refinish the affected panels. The labor hours listed on the estimate are in line with the work required for this damage. The invoices reviewed show no repeated charges. No prior damage to the vehicle is known from the records available, and the repair scope is limited to the damage from this loss.