Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-834875
Estimate date:	November 17, 2023
Customer:	Taylor Johnson
Phone:	713-555-8343
Insurance claim:	C-1102
Vehicle:	2020 Jeep Cherokee
VIN:	LX74DCPD234UD0009
License plate:	KQX6775

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$824.88
Right front door shell	1	$824.31
Left quarter panel	1	$796.90
Body labor	23.1 hrs	$1,568.63
Paint and materials		$1,129.52
TOTAL		$5,144.24

Appraiser remarks

The rear quarter panel and bumper cover on the left side show the bulk of the crush and crease damage, which lines up well with the impact described for a vehicle turning left into traffic. A few older scratches are visible on the same panel and may predate this loss; they are ntoed here but are not included in the repair scope. The labor hours requested fit the extent of the damage, and the parts and charges on the submitted invoices show no repeated entries. The plan is to replace the bumper cover, repair and refinish the quarter panel, and recalibrate the affected sensor once the parts arrive.