Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-507309
Estimate date:	8-6-23
Customer:	Jeremy Quinn
Phone:	713-555-8640
Insurance claim:	C-1107
Vehicle:	2010 Nissan Altima
VIN:	6XMD2J1PXH54M3198
License plate:	50-KZ84

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,160.05
Front bumper cover	1	$797.55
Left front fender	1	$559.30
Body labor	29.8 hrs	$2,029.52
Paint and materials		$1,129.87
TOTAL		$5,676.29

Appraiser remarks

Vehicle inspected at the body shop following a sideswipe that occurred while the insured was changing lanes. The damage to the right rear quarter panel, rear bumper cover and adjacent door skin is largely consistent with the reported impact, with scuffing and paint transfer running in the same direction as described. No prior damage to this vehicle is known, and the repair plan calls for replacing the bumper cover, refinishing the qaurter panel and blending the door. The labor hours listed fit the work required for these panels. The shop invoices show no repeated charges for the same operations. Recommend approval of the repair as estimated.