Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-468753
Estimate date:	2025-01-22
Customer:	Debbie Ellison
Phone:	346-555-9014
Insurance claim:	C-1117
Vehicle:	2016 Kia Sorento
VIN:	
License plate:	G77-UXL

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$835.57
Right front door shell	1	$632.21
Hood panel	1	$580.58
Body labor	25.2 hrs	$1,712.70
Paint and materials		$684.99
TOTAL		$4,446.05

Appraiser remarks

The left rear quarter panel and rear door on the driver side show crush and creasing consistent with a side impact at an intersection, and the pattern of deformation follows the direction of the reported collision. A few older scratches along the lower rocker area appear to predate this loss and have been noted separately. The proposed repair plan calls for panel replacement, refinishing, and alignment checks on the rear door hinge. The labor hours listed fit the scope of the damage, and the parts and paint charges reflect a single set of work with no repeated line items. Final supplements will be reviewed once the vehilce is on the lift.