Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-447496
Estimate date:	12-25-23
Customer:	Hector Hicks
Phone:	346-555-7969
Insurance claim:	C-1119
Vehicle:	2019 Toyota Camry
VIN:	36PNSVZCXCR182395
License plate:	0J-CEUO

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$847.87
Right front door shell	1	$541.34
Front bumper cover	1	$546.11
Body labor	21.1 hrs	$1,433.87
Paint and materials		$1,023.94
TOTAL		$4,393.13

Appraiser remarks

The vehicle shows a left-front impact consistent with the reported collision during a left turn. Damage to the front bumper cover, left headlamp assembly, fender and hood edge liens up with the described sequence, and the lower control area shows scuffing that agrees with the contact point. No prior damgae to the vehicle is known to this office. Labor hours requested fit the scope of the listed repairs. Two similar charges submitted on the same day are under review and will be verified with the shop before payment is approved. Repair plan: replace bumper cover, headlamp and fender, refinish hood edge, and perform a wheel alignment check.