Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-160043
Estimate date:	2023-03-28
Customer:	Laurie Gonzales
Phone:	
Insurance claim:	C-1120
Vehicle:	2014 Jeep Cherokee
VIN:	1W71NSLY7YX3L4396
License plate:	OGT 316

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,102.49
Front bumper cover	1	$860.20
Left quarter panel	1	$704.03
Body labor	43.2 hrs	$2,075.25
Paint and materials		$1,182.00
TOTAL		$5,923.97

Appraiser remarks

The rear quarter panel and bumper cover show the main damage, and the pattern fits the side-swipe impact as reported. The left rear door shows a crease that runs toward the wheel arch, which is consistent with the same contact. Labor hours appear a little high for this scope, so the line items need a second look before approval. Two similar charges posted on the same day are under review with the shop. No prior damage to this vehicle is known. Proceed with parts ordering once the labor and charge questions are settled.