Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-841802
Estimate date:	24 Dec 2023
Customer:	Steven Moore
Phone:	346-555-8633
Insurance claim:	C-1123
Vehicle:	2022 Nissan Altima
VIN:	XVBT7C80XBE9Z2941
License plate:	AYM-2539

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$214.13
Left front fender	1	$296.33
Headlamp assembly	1	$179.70
Body labor	6.6 hrs	$449.04
Paint and materials		$328.20
TOTAL		$1,467.40

Appraiser remarks

The rear bumper cover is cracked across the lower section, with the left taillight assembly broken and the trunk lid edge scraped in a line that fits the reported contact with another car in a parking lot. The damage pattern lines up with the impact as described. Plan is to replace the bumper cover, the taillight assembly, and refinish the trunk lid, with labor hours that fit the scope of this damage. No prior damage to this vehicle is known from our records or the owner's account. The invoices submitted show no repeated charges for the same work, and the estimate is ready for review.