Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-419223
Estimate date:	09/02/2023
Customer:	Jessica Thompson
Phone:	832-555-1368
Insurance claim:	C-1127
Vehicle:	2022 Jeep Cherokee
VIN:	3H3TW5KP1VER76597
License plate:	

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,333.79
Rear body panel	1	$1,184.32
Rear bumper cover	1	$997.76
Body labor	30.8 hrs	$2,094.70
Paint and materials		$1,275.63
TOTAL		$6,886.20

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp housing is broken, consistent with the reported impact. Crush marks run along the trunk lid and the lower panel, and the damage pattern lines up with the collision as described. The planend repair is to replace the bumper cover and tail lamp assembly, refinish the trunk lid, and repair the rear panel where it was pushed inward. Labor hours fit the extent of the damage. The billing records show no repeated charges. A photo from an earlier inspection already shows a dent in the same rear quarter panel, so that prior damage has been separated out of this estimate and is not included in the repair scope.