Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-643525
Estimate date:	14 Jun 2024
Customer:	Matthew Cervantes
Phone:	
Insurance claim:	C-1131
Vehicle:	2011 Chevrolet Malibu
VIN:	J2M384MR63B7F3586
License plate:	NW-6946

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,695.43
Right front door shell	1	$1,052.48
Hood panel	1	$992.88
Body labor	40.8 hrs	$2,771.34
Paint and materials		$1,813.08
TOTAL		$8,325.21

Appraiser remarks

The vehicle was inspected at the body shop following a sideswipe that occurred while changing lanes. The damage on the rear quarter panel and the adjacent door is largely consistent with the reported impact, showing a continuous path of scuffing, creasing, and paint transfer. A few small scratches lower on the bumper appear weathered and may predate this incident. The proposed repair plan covers panel replacement, refinishing, and blending to match the surrounding paint, and the labor hours listed fit the scope of the visible damage. The line items reivewed show no repeated charges.