Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-193972
Estimate date:	2025-03-16
Customer:	Jeffery Fry
Phone:	281-555-0376
Insurance claim:	C-1139
Vehicle:	2018 Hyundai Elantra
VIN:	FCPCPXL29B8S19628
License plate:	RPY-578

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$445.72
Right front door shell	1	$291.66
Left front fender	1	$290.22
Body labor	10.1 hrs	$689.93
Paint and materials		$394.01
TOTAL		$2,111.54

Appraiser remarks

The vehicle was inspected at the body shop on the claimant's report of a sideswipe during a lane change. The dents and scrapes found are located on the opposite side of the vehicle from the reported point of contact and sit at a noticeably different height, so the pattern does not line up with the account given. The repair invoices show each line item billed once with no repeated charges, and the labor hours listed are consistent with the extent of the damage found. No prior damage to this vehicle is known from the records reviewed. The recommended plan is to replace the affected door panel, repair the adjacent quarter panel, and refinish the blended area, with the estimate to be reviewed against the photographs taken at inspection.