Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-483384
Estimate date:	1 Sep 2023
Customer:	Lacey Greene
Phone:	281-555-8794
Insurance claim:	C-1147
Vehicle:	2012 Toyota Camry
VIN:	MTVENATE4XUFP5951
License plate:	DH0 2286

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$370.76
Left quarter panel	1	$450.01
Right front door shell	1	$250.70
Body labor	11.9 hrs	$806.05
Paint and materials		$571.11
TOTAL		$2,448.63

Appraiser remarks

The vehicle presents a rear quarter panel dent with a cracked taillight lens and scuffing along the rear bumper cover, all of which lines up with the impact as it was described to us. The repair plan calls for replacing the bumper cover, refinishing the quarter panel, and swapping the lamp assembly, with labor hours set to match the extent of the deformation. Nothing on the car points to earlier damage in this area, and the invoices we reviewed show no duplicated line items or repeated charges. The estimate is ready for approval once the parts sourcing is confirmed.