White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-803595
Estimate date:	January 5, 2025
Customer:	Sarah Stevens
Phone:	832-555-3674
Insurance claim:	C-1149
Vehicle:	2024 Nissan Altima
VIN:	58GXLJSU89E4U2482
License plate:	EXC 168

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,235.92
Hood panel	1	$973.13
Left quarter panel	1	$800.56
Body labor	32.4 hrs	$2,200.62
Paint and materials		$1,019.44
TOTAL		$6,229.67

Appraiser remarks

Appraiser's remarks: The rear driver-side quarter panel and rear door show crush and creasing consistent with a side impact at an intersection, and the pattern of deformation matches the account given. The repair plan calls for panel replacement, refinishing, and a frame alignment check, with labor hours that fit the extent of the damage. Billing on the submitted invoices shows no repeated charges. However, prior records show the same major structural damage from an earlier accident that was never reported, and it is now being presented as new. This discrepancy needs review before the claim is settled.