Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-436139
Estimate date:	04/12/2023
Customer:	Ashley Krause
Phone:	281-555-3901
Insurance claim:	C-1153
Vehicle:	2015 Toyota Camry
VIN:	NX2ELL170GHLU9968
License plate:	OXW8174

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$804.13
Right front door shell	1	$768.99
Left front fender	1	$610.02
Body labor	28.5 hrs	$1,935.71
Paint and materials		$1,095.55
TOTAL		$5,214.40

Appraiser remarks

Vehicle presented after a side impact at an intersection. Damage is concentrated on the driver-side door panel, rear quarter panel and adjacent sill, with the impact pattern consistent with the account given. Repair plan calls for door replacement, quarter panel repair and refinishing, plus sill and trim reattachment. Labor hours submitted are in line with the damage found. Shop billing shows no repeated charges for the same operations. Inspection found no sign of earlier damage to these panels, and no proir loss on this vehicle is known to us. Recommend approval of the repair as presented.