Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-709554
Estimate date:	7-2-23
Customer:	Randall Duncan
Phone:	281-555-7837
Insurance claim:	C-1155
Vehicle:	2019 Jeep Cherokee
VIN:	
License plate:	4-4183F

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$503.19
Left quarter panel	1	$502.49
Headlamp assembly	1	$574.74
Body labor	16.0 hrs	$1,086.43
Paint and materials		$576.99
TOTAL		$3,243.84

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The primary damage is to the driver-side front door, rear quarter panel and the adjacent sill, with a crushed door beam and cracked window glass. Most of what I observed lines up with the impact as described. The estmiate has been reviewed against the bills, and nothing appears billed twice. Labor hours are consistent with the extent of the work. No prior damage to this vehicle is on record. Recommended plan: replace the door shell and quarter panel, repair the sill, install new glass, and refinish the affected panels to match.