Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-173435
Estimate date:	8-17-23
Customer:	Kenneth Brown
Phone:	713-555-0159
Insurance claim:	C-1161
Vehicle:	2019 Honda Civic
VIN:	PAVBPYEC27A3N6740
License plate:	4ZI 769

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,386.83
Left quarter panel	1	$1,087.13
Hood panel	1	$1,062.95
Body labor	30.4 hrs	$2,068.48
Paint and materials		$1,169.49
TOTAL		$6,774.88

Appraiser remarks

Inspection of the left rear quarter panel and rear door shows crumpling and paint transfer consistent with a side impact at an intersection. Most of the deformation lines up with the account given, and the repair plan is to replace the rear door, straighten the quarter panel, and refinish both panels. The labor hours requested match the extent of the damage. Our review of the invoices found no repeated charges for the same operation. A few faint scratches on the rear bumper appear older than this crash and have been ntoed but are not included in the repair scope. Recommend approval of the plan as written.