Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-401256
Estimate date:	05/30/2023
Customer:	William Lyons
Phone:	713-555-2232
Insurance claim:	C-1162
Vehicle:	2024 Honda Civic
VIN:	UT0SNSCR1RZYC0253
License plate:	ZB 9225

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$743.45
Headlamp assembly	1	$636.17
Left front fender	1	$406.77
Body labor	19.3 hrs	$1,314.57
Paint and materials		$506.34
TOTAL		$3,607.30

Appraiser remarks

The vehicle was inspected at the body shop following a low-speed head-on collision. The front bumper cover, hood leading edge, and both headlamp assemblies show fresh crush and fracture consistent with the reported impact, and the radiator support shows matching deformation. A few older scratches on the lower rear quarter panel may predate this loss and have been noted separately from the repair scope. The proposed plan covers replacement of the damaged front components, refinishing, and a standard frame check. The labor hours listed fit the damage observed, and the parts and charges on the submitted invoices show no repeated entries.