Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-872047
Estimate date:	May 9, 2023
Customer:	Alexander Murphy
Phone:	832-555-1208
Insurance claim:	C-1174
Vehicle:	2010 Jeep Cherokee
VIN:	MN28CDRV2RV5H2115
License plate:	FRF-464

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,197.58
Headlamp assembly	1	$1,031.94
Right front door shell	1	$567.49
Body labor	29.5 hrs	$2,002.66
Paint and materials		$1,076.26
TOTAL		$5,875.93

Appraiser remarks

The vehicle shows crush and paint trnasfer along the driver-side rear quarter panel, with the rear door and sill deformed inward and the wehel arch lip bent. The pattern of deformation lines up well with a side impact at an intersection as described, and the damage runs in a continuous path with no sign of separate or older events. Repair work is planned as panel replacement for the quarter panel, straightening of the door frame, and refinishing of the adjacent surfaces. The labor hours requested are in line with the extnet of the damage shown in the photographs. Invoices reviewed so far cnotain no duplicated line items, and no prior damage to this vehicle has come to light.