Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-883507
Estimate date:	March 14, 2025
Customer:	James Roth
Phone:	713-555-1658
Insurance claim:	C-1176
Vehicle:	2023 Jeep Cherokee
VIN:	CEP21TGL5AJ3X5804
License plate:	286R2

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,371.34
Headlamp assembly	1	$749.76
Left quarter panel	1	$945.18
Body labor	45.3 hrs	$2,175.28
Paint and materials		$983.74
TOTAL		$6,225.30

Appraiser remarks

Appraiser's remarks: The vehicle shows a side impact to the driver's door, rear quarter panel, and adjacent rocker area, with crush and paint transfer consistent with the reported intersection collision. Most of the damage lines up well with the impact described. Repairs are planned as door and quarter panel replacement, with refinishing and a sensor recalibration. The lbaor hours look a little high for this scope, so a line-by-line review is suggested. The invoices show no repeated charges. No prior damage to the vehicle is known from our records.