Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-666005
Estimate date:	2024-02-21
Customer:	Vincent Bryant
Phone:	346-555-5243
Insurance claim:	C-1188
Vehicle:	2014 Ford F-150
VIN:	HMZET5ZCXACR37448
License plate:	502 5II

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,262.05
Left quarter panel	1	$1,076.21
Front bumper cover	1	$1,079.45
Body labor	42.6 hrs	$2,899.44
Paint and materials		$1,083.45
TOTAL		$7,400.60

Appraiser remarks

Inspection confirms damage to the front bupmer cover, the radiator support, and the left headlamp assembly, with crush and scuffing that line up with a low-speed frontal impact. The pattern of the marks agrees with the account given of how the collision happened. Repair will involve replacing the bumper cover and headlamp, straightening the support, and refinishing the affected panels. The labor hours requested are in line with the work needed to restore these parts. Shop invoices reviewed so far show no duplicated line items. Nothing in our records points to earlier damage on this vehicle in the same areas.