Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-117499
Estimate date:	June 12, 2023
Customer:	Sara Davis
Phone:	713-555-2662
Insurance claim:	C-1193
Vehicle:	2023 Nissan Altima
VIN:	TWBUGK458Z8KD9892
License plate:	4GK2562

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,725.66
Front bumper cover	1	$1,129.92
Right front door shell	1	$946.01
Body labor	72.9 hrs	$3,497.48
Paint and materials		$1,744.95
TOTAL		$9,044.02

Appraiser remarks

The vehicle was struck while turning left, and the damage seen on the front quarter panel, bumper cover, and left headlamp assembly lines up well with that impact direction. Parts and labor are itemized on the estimate, and the repair plan calls for replacing the bumper cover, refinishing the fender, and ailgning the headlamp mounts. The labor hours run a little high for this level of damage, so a second look at the blend and refinish times may be worthwhile. No prior damage to the vehicle is known, and the repair invoices show no repaeted charges for the same work.