Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-218546
Estimate date:	29 Apr 2025
Customer:	Zachary Jenkins
Phone:	281-555-5435
Insurance claim:	C-1194
Vehicle:	2013 Honda Civic
VIN:	2N6ZZNVV2MXBZ8280
License plate:	30O Q18

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,223.70
Front bumper cover	1	$1,088.73
Hood panel	1	$998.69
Body labor	30.3 hrs	$2,062.63
Paint and materials		$1,384.63
TOTAL		$6,758.38

Appraiser remarks

Inspection of the front end shows a cracked bumper cover, a bent upper radiator support, and a damaged hood latch, all consistent with the reported low-speed frontal impact. The pattern and location of the crush line mtach the described collision, and no older damage was found or reported on this vehicle. The repair plan replaces the bumper cover, hood latch, and radiator support, with a standard alignment check. The labor hours listed fit the work required, and the parts and invoices submitted contain no repeated charges. Recommend approval of the estimate as written.