Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-880083
Estimate date:	April 21, 2023
Customer:	Stacy Chan
Phone:	713-555-1972
Insurance claim:	C-1198
Vehicle:	2021 Toyota Camry
VIN:	V5N7RE0E10MT50477
License plate:	595338

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,871.54
Right front door shell	1	$1,067.20
Headlamp assembly	1	$1,111.58
Body labor	45.9 hrs	$3,119.23
Paint and materials		$1,540.12
TOTAL		$8,709.67

Appraiser remarks

The vehicle presents a rear quarter panel dent and a bumper cover crack, with secondary scuffing along the lower door edge. The dent location sits on the opposite side and at a higher point than the impact described in the claim, so the damage pattern and the reported account do not line up, and this should be reviewed before payment. Repair billing shows no repeated line items, and the labor hours requested are consistent with the work needed on these panels. Nothing in our records or the vehicle history indicates earlier damage to these areas. Recommended plan: replace the bumper cover, repair the quarter panel, refinish affected surfaces, and recheck after the first-stage teardown.