Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-150904
Estimate date:	2025-03-19
Customer:	Ashley Butler
Phone:	832-555-0236
Insurance claim:	C-1204
Vehicle:	2010 Kia Sorento
VIN:	P2URHZXA18E346487
License plate:	KKL 464

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$844.60
Hood panel	1	$882.03
Left quarter panel	1	$630.21
Body labor	23.6 hrs	$1,608.12
Paint and materials		$778.41
TOTAL		$4,743.37

Appraiser remarks

The vehicle shwos damage to the rear bumper cover, the left quarter panel, and the tail lamp assembly, with scuffing that runs along the left side. Most of what we see lines up with the impact as it was described to us. The repair plan calls for replacing the bumper cover and lamp assembly, straightening and refinishing the quarter panel, and blending the paint into adjacent panels. The labor hours on the estimate match the scope of the work. The parts and charges on the supporting invoices appear once each, with no repeated entries. We have no record or sign of earlier damage to this vehicle, so the repairs above are limited to this incident.