Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-142325
Estimate date:	12-17-23
Customer:	Paul Wells
Phone:	346-555-3618
Insurance claim:	C-1215
Vehicle:	2010 Kia Sorento
VIN:	1MN223M443TBP9083
License plate:	WSY 805

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$973.32
Headlamp assembly	1	$920.28
Left front fender	1	$1,146.47
Body labor	41.6 hrs	$1,995.07
Paint and materials		$1,468.59
TOTAL		$6,503.73

Appraiser remarks

Appraiser's remarks: The right rear quarter panel shows a long scrape with paint transfer and a dented rear door edge, consistent with a sideswipe during a lane change. The damage pattern lines up with the ipmact as described, and no earlier damage to this vehicle is known. The shop plan calls for panel replacement, refinishing, and a door adjustment. Labor hours appear slightly high for this scope, so I have asked the shop to review the time allowances before approval. The invoices reviewed show no repeated charges.