Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-593661
Estimate date:	2024-12-19
Customer:	Virginia Bell
Phone:	
Insurance claim:	C-1222
Vehicle:	2015 Nissan Altima
VIN:	
License plate:	Z 053256

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,214.39
Right front door shell	1	$1,219.42
Hood panel	1	$1,029.67
Left quarter panel	1	$1,214.39
Body labor	32.1 hrs	$2,185.87
Paint and materials		$1,063.12
TOTAL		$7,926.86

Appraiser remarks

The left rear quarter panel and rear door show deep creasing, and the intrusion pattern on the side sill lines up with the impact described in the claim. Structural measurements taken on the frame rail are within tolerance for the reported side strike, and no prior collision repairs or unrelated damage were found on the vehicle. The proposed plan calls for replacing the rear door and quarter panel, straightening the sill, and refinishing the affected area, with labor hours that fit the scope of this damage. One item on the provider's billing record appears twice for the same service, and the shop has confirmed that the second entry was a repeat that should be removed before payment.