Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-899106
Estimate date:	2025-01-13
Customer:	Meghan Green
Phone:	832-555-6423
Insurance claim:	C-1229
Vehicle:	2012 Kia Sorento
VIN:	CB4P1UN3XMGHN6961
License plate:	9M I4110

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$202.98
Hood panel	1	$227.35
Headlamp assembly	1	$192.91
Body labor	7.6 hrs	$515.85
Paint and materials		$273.77
TOTAL		$1,412.86

Appraiser remarks

The vehicle presents front quarter damage on the driver side consistent with a collision while turning left, including a cracked headlamp assembly, a bent front bumper bar, and scuffing along the fender leading edge. The damage pattern lines up with the impact as described. The repair plan calls for replacing the headlamp and bumper cover, straightening the fender brace, and refinishing the affected panels. The labor hours requested fit the extent of the damage, and the parts and invoices submitted show no repeated charges. No prior damage to this vehicle is known from the records reviewed.