Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-394267
Estimate date:	16 Nov 2023
Customer:	Tracey Miller
Phone:	832-555-4768
Insurance claim:	C-1231
Vehicle:	2019 Kia Sorento
VIN:	LSFBBSY52M8BN1178
License plate:	291-FVO

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$453.23
Front bumper cover	1	$364.75
Hood panel	1	$471.13
Body labor	13.1 hrs	$892.72
Paint and materials		$533.85
TOTAL		$2,715.68

Appraiser remarks

The rear passenger quarter panel and rear door on the driver's side show scraping, a crease along the lower edge, and a cracked taillight lens, all consistent with a sideways contact at low speed while the other vehicle moved into the adjacent lane. The damage pattern lines up with the account given of the incident. The repair plan calls for replacing the taillight assembly, straightening and refinishing the rear door, and blending the quarter panel into the adjacent paint. The labor hours requested fit the work described. Parts and paint charges on the invoices appear once each, with no duplicated line items. Nothing in the vehicle's history or the shop's records suggests earlier damage to these areas.