Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-380703
Estimate date:	01/06/2024
Customer:	Warren Fletcher
Phone:	346-555-7849
Insurance claim:	C-1233
Vehicle:	2022 Kia Sorento
VIN:	5Z2Z24G22BV0H9336
License plate:	759 KEF

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$585.93
Left quarter panel	1	$525.63
Headlamp assembly	1	$417.37
Body labor	55.0 hrs	$1,210.34
Paint and materials		$716.90
TOTAL		$3,456.17

Appraiser remarks

Inspection of the left front and fender area shows crush and paint transfer that fit a side-angle stirke during a left turn, and most of the visible damage follows that impact pattern. The billing records reviewed so far contain no repeated line items. However, the labor hours on this estimate run roughly three times what a repair of this scope normally requires, so the shop should justify each block of time before approval. No prior damage to the vehicle is known to this office. Proposed plan: replace the bumper cover, repair the fender, refinish adjacent panels, and recheck alignment after the work is complete.