# Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-112846 |
| **Estimate date:** | 25 Feb 2024 |
| **Customer:** | Richard Smith |
| **Phone:** | 832-555-1052 |
| **Insurance claim:** | C-1236 |
| **Vehicle:** | 2015 Toyota Camry |
| **VIN:** | EW9RXMJN2J6G97690 |
| **License plate:** | 95YB6 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Front bumper cover | 1 | $257.02 |
| Left front fender | 1 | $336.30 |
| Right front door shell | 1 | $190.40 |
| Body labor | 31.9 hrs | $701.39 |
| Paint and materials | | $418.26 |
| TOTAL | | $1,903.37 |

### Appraiser remarks

The vehicle inspection supports the reported sideswipe during a lane change. The damage sits along the right rear quarter panel and door, with scuffing and paint transfer in a consistent line, and it matches the described impact. No earlier damage to the vehicle is known, and the repair bills show no repeated charges. However, the proposed labor hours are far higher than this damage requires, roughly three times what a normal estimate would allow. Recommend the shop justify each labor line item, and approve the repair plan once the hours are revised to reflect the actual scope of work.