Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-197355
Estimate date:	April 2, 2023
Customer:	Tonya Trujillo
Phone:	832-555-9075
Insurance claim:	C-1240
Vehicle:	2011 Toyota Camry
VIN:	518PKKKK6VH4P7920
License plate:	WRO 032

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,469.77
Front bumper cover	1	$1,208.65
Left front fender	1	$964.14
Body labor	31.5 hrs	$2,143.33
Paint and materials		$1,345.68
TOTAL		$7,131.57

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including a cracked bumper cover, displaced grille, and damage to the hood leading edge and headlamp mounts. Visible crush and contact points line up with the described collision, and no earlier damage to the vehicle is known from the file or the owner's account. The repair plan calls for replacing the bumper cover and hood, refinishing the affected panels, and replacing the headlamp assemblies, with a radiator support check. The labor hours submitted fit the scope of this damage. The shop's invoices show no repeated charges for the same operations. Recommend approval of the estimate as written.