Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-354527
Estimate date:	25 Jun 2023
Customer:	Brittany Jackson
Phone:	832-555-4152
Insurance claim:	C-1247
Vehicle:	2012 Kia Sorento
VIN:	EA6HP74N3687H8998
License plate:	DPW-834

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,274.07
Left quarter panel	1	$1,144.90
Left front fender	1	$574.09
Body labor	33.7 hrs	$2,291.23
Paint and materials		$924.79
TOTAL		$6,209.08

Appraiser remarks

Upon inspection of the vehicle following the side impact at the intersection, the driver's side door, rear quarter panel and adjacent sill show deformation consistent with the reported collision. Some of the lower rocker and wheel-well damage may or may not stem from this event, and the shop should confirm that point before final approval. The repair plan calls for panel replacement, refinishing and frame measurement, and the labor hours requested match the scope of the visible damage. Review of the invoices shows no repeated charges for the same operations. No earlier damage to the vehicle is known from the records provided.