White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-795993
Estimate date:	April 3, 2024
Customer:	Jennifer Watts
Phone:	832-555-0891
Insurance claim:	C-1251
Vehicle:	2018 Nissan Altima
VIN:	41W45ZD951R715661
License plate:	7ZHZ 00

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,725.56
Right front door shell	1	$1,346.62
Left front fender	1	$790.50
Body labor	59.8 hrs	$2,868.75
Paint and materials		$1,689.78
TOTAL		$8,421.21

Appraiser remarks

The rear quarter panel and bumper cover on the left side show the crush and scuffing pattern expected from a side impact during a left turn, and the paint transfer is consistent with the reported contact point. No earlier damage to this vehicle is known from the file or the owner's history. The repair plan calls for replacing the bumper cover, repairing and refinishing the quarter panel, and replacing the left taillamp assembly. The shop's labor hours run a little high for this scope of work, so I recommend a line-by-line review before approval. The invoices submitted show no repeated charges.