Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-464446
Estimate date:	2023-07-15
Customer:	Brooke Jones
Phone:	
Insurance claim:	C-1252
Vehicle:	2016 Nissan Altima
VIN:	KABZY1YC2UE3R9004
License plate:	OYN 296

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$612.44
Left front fender	1	$746.36
Headlamp assembly	1	$516.36
Body labor	57.6 hrs	$1,267.38
Paint and materials		$920.61
TOTAL		$4,063.15

Appraiser remarks

The rear quarter panel and bumper cover show crush and scuffing that fit a left turn impact from the other vehicle, and the pattern agrees with the account given. Invoices on file show no repeated charges. However, the labor hours requested run roughly three times what this damage normally clals for, so the plan should be reviweed line by line before approval. No prior damage to this vehicle is known. Recommend replacing the quarter panel and bumper cover, refinishing adjacent areas, and resubmitting a revised labor count.