Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-657622
Estimate date:	6-15-23
Customer:	Benjamin Brown
Phone:	832-555-7870
Insurance claim:	C-1257
Vehicle:	2023 Jeep Cherokee
VIN:	L99T9K6M5AZ7S2893
License plate:	1-K7731

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$888.17
Right front door shell	1	$685.73
Hood panel	1	$561.14
Body labor	20.9 hrs	$1,419.29
Paint and materials		$1,011.39
TOTAL		$4,565.72

Appraiser remarks

The vehicle presents with damage concentrated on the rear bumper cover, the left quarter panel, and the adjacent taillight assembly, which lines up well with the low-speed rear-corner contact described at the scene. The proposed repair plan calls for replacing the bumper cover and taillight, refinishing and blending the quarter panel, and replacing the rear reinforcement bar. Labor hours requested fit the extent of the work shown in the photos, and the parts list and charges on the invoice are consistent without any duplicated line items. Nothing in the file suggests prior damage to this area, so the repairs are estimated as a single, collision-related scope.