Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-850410
Estimate date:	December 7, 2023
Customer:	Amy Anderson
Phone:	346-555-4545
Insurance claim:	C-1258
Vehicle:	2023 Nissan Altima
VIN:	
License plate:	

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,873.15
Right front door shell	1	$1,058.28
Left quarter panel	1	$1,001.25
Body labor	57.5 hrs	$2,759.41
Paint and materials		$1,929.39
TOTAL		$8,621.48

Appraiser remarks

The vehicle presents front-left corner damage consistent with the reported impact while turning left, including a cracked bumper cover, a bent headlamp bracket, and a dented fender with a torn support. The damage pattern agrees with the account given. Some older scratches along the lower door panel may predate this loss and have been noted separately. The repair plan calls for replacing the bumper cover, headlamp assembly, and fender, with refinishing and a wheel alignment check. Labor hours appear slightly high for the listed damage and should be reviewed against standard times. Two similar charges posted on the same day are currently being verified with the shop before payment.